



09674422, 092700

FIG. 2




09671422, 092700

FIG. 3A




002260" 22472960

FIG. 3B




002260 "247" 960

FIG. 3C


09671422, 092700

FIG. 4A




09674422 092700

FIG. 4B




09671422 092700

FIG. 4C




09671422, 092700

FIG. 5A


007260" 2247960

FIG. 5B




002260" 2247/960

FIG. 5C




09674422 092700

FIG. 5D



09671422 092700

FIG. 6A



09671422, 092700

FIG. 6B






FIG. 6C




09571422, 092700

FIG. 7A




00/260" 24T/960

FIG. 7B




002260" 22472960

FIG. 8A



09674422, 092700

FIG. 8B



09671422, 092700

FIG. 9




FIG. 10





FIG. 11



09671422, 092700




FIG. 12

System Manager Command Processing




FIG. 13

09671422 092700

System Manager Command Processing




FIG. 14

09671422, 092700

Cash Status Event Processing




FIG. 15

09673422 092700

00/260" 227/960




FIG. 16




FIG. 17




FIG. 18




FIG. 19

Component Factory Startup




FIG. 20

09671422, 092700

Component Factory Startup




FIG. 21

09674422, 092700

Instrument Rendezvous




FIG. 22

09671422, 092700